


**GMC MOTORHOMES
INTERNATIONAL CLUB**

GMC

IGNITION SYSTEM



**Prepared by: Duane M Simmons
Bob Lamey
Graphics Assistance: Zay Brand**

**Marion, North Carolina Convention
October 11-17, 1998**

The contents of this document are based upon personal experience gained by "Hands-On" vehicle maintenance over many years. They are "One Man's" viewpoint & do not represent authorized data pertaining to the GMC Motorhome. It is the Reader's responsibility to establish His/Her position associated with each subject matter before vehicle repair &/or modifications are accomplished.

Copyright 1988

HEI GENERAL TEST PROCEDURE (CONT'D)
(ON VEHICLE MODULE TEST)


- **MODULE TEST:**
- **CONNECT GROUNDED HEI TESTER TO DISTRIBUTOR'S CENTER TERMINAL**
- **REMOVE PICK-UP COIL MODULE CONNECTOR & TURN ON IGNITION SWITCH**
- **CONNECT TEST LITE TO +12v SOURCE**
 - **MOMENTARILY TOUCH THE OTHER TEST LITE LEAD TO THE MODULE'S SMALL TERMINAL**
 - **SPARK AT HEI TESTER INDICATES PICK-UP COIL IS NOT WORKING : REMOVE DIST. & REPLACE PICK-UP COIL**
 - **NO SPARK AT HEI TESTER INDICATES MODULE IS NOT WORKING: REPLACE MODULE**

Note: Clean & Check Terminals for Tightness Before Test

3

THE IGNITION SYSTEM


POINT TYPE IGNITION




4

TRANSISTOR IGNITION SYSTEMS


MAGNETIC PULSE TYPE



TRANSISTOR IGNITION SYSTEM




MAGNETIC PULSE DISTRIBUTOR




6


6



Integral HEI Distributor




Module and Pulse Generator



Pulse Generator Construction


7

AS ENGINE SPEED INCREASES **SPARK MUST BE TIMED EARLIER**




- Empirically Determined to be Limited to Approx. 36 Degrees for GMC Motorhome with 8.5:1 Compression Ratio & RV Cam (465/403 Engine).

SPARK ADVANCE



• Empirically Determined to be Limited to Approx. 36 Degrees for GMC Motorhome with 8.5:1 Compression Ratio & RV Cam (465/403 Engines).

COMPARISON OF AVAILABLE AND REQUIRED SECONDARY VOLTAGE



HEI ADVANTAGE Over POINT SYSTEM

- PROVIDES 35,000 VOLTS SECONDARY
- INCREASES SPARK PLUG LIFE
- 40% MORE VOLTAGE AT THE SPARK PLUGS
- 85% MORE ENERGY LEVEL
- LOWER SCHEDULED MAINTENANCE

Note: Introduced by GM in 1974 Cars

ELECTRONIC IGNITION UPGRADE *CALIFORNIA ACCEPTABLE

- *ELECTRONIC IGNITIONS
E I systems that replace original point type systems are acceptable as long as the Vacuum & Centrifugal Advance controls are maintained.
FOR EXAMPLE, a HEI Ignition Distributor could be used to replace the points distributor in a 1972 Chevrolet if the advance controls were maintained.*

Note: *Reference California Smog Requirement, Appendix K-
Smog Check Requirements For Modifications & Add-On Parts.
Dated: Rev 2 (8-92)

HEI COMPONENT MISS-MATCH PROBLEM

GM INTRODUCED IDENTICALLY SHAPED COMPONENTS FOR HEI THAT FUNCTIONALLY ARE NOT INTERCHANGEABLE:

IGNITION COIL:

Bk-Red-White Leads
(White Tach Lead)



PICK-UP COIL:

Black Connector Body
(Or Blue Tie)

Bk-Red-Yellow Leads
(Yellow Tach Lead)



Yellow Connector Body
(Or Yellow Tie)

MISS-MATCH COMPONENTS CREATE ERRATIC TIMING (JITTER) & HARD TO START CONDITIONS. IT'S **BEST** TO PROPERLY MATCH COMPONENTS. HARD TO DETECT (SCOPE REQUIRED)

NOTE: -MAGNETIC POLARITY DIFFERENT

13

13

GMC MOTOR HOME DISTRIBUTOR SPECIFICATIONS

	Early 455 Points	FED 455 HEI	CAL 455 HEI	FED 403 HEI	CAL 403 HEI	*Custom I 455/403	*Custom II 455/403
Dist. #	1112172	1112893	1112945	1103267	1103309	xxxxxxxx	xxxxxxxx
Mech. Adv. (Deg.)							
Start	0 @ 1100	0 @ 900	0 @ 900	0 @ 1100	0 @ 2200	0 @ 1000	0 @ 800
Mid.	9 @ 2000	9 @ 2000	9 @ 2000	9 @ 2000	11 @ 2600	8 @ 1100	10 @ 2000
Max.	16 @ 3400	16 @ 3400	16 @ 3400	16 @ 3400	16 @ 3400	18 @ 2900	19 @ 3100
Vac. Adv. #	1973408	1973523	1973560	1973609	1973634	1973577	1973577
Start (" Hg)	8"-10"	8"-10"	14"-16"	4"-6"	11"	6"	6"
Max. (" Hg)	19"-20"	19"-20"	18"-19"	7"-8"	14"	9"	8"
Max. Adv. (Deg.)	24	24	10	8	10	10	10"
Ignit. Timing (Deg.)	8 @ 1100	8 @ 1100	8 @ 1100	12 @ 1100	12 @ 2000	8 @ 850	8 @ 850
Total Adv. (Deg.)							
Mech. + Vac. + I	48	48	34	38	38	36	37
**Effective*	24	21	18	30	12	32	29

Note:


* Not Certified for Smog Controlled Vehicle

** "Effective" is the Total Advance @ 2200 RPM & 11" Vac. (65 MPH Cruise)



14


Centrifugal Advance Vs RPM GMC Specifications



Note: • Not Certified for Smog Control
9/26/94

15

Vacuum Advance Vs Vacuum GMC Specifications



Note: • Not Certified for Smog Control

16

IGNITION SYSTEM FAILURES - GENERAL

- **BAD IGNITION WIRES**
 - High Resistance & Voltage Leakage/Breakdown
- **LIMITED MECHANICAL ADVANCE**
 - Worn Pins/Weights (Shaft/Bearing Wear)
- **LIMITED VACUUM ADVANCE**
 - Diaphragm Failure (Hole)
 - Sticky/Stuck Bearing
- **DISTRIBUTOR SHAFT BEARING WORN**
 - Erratic/Change of Ignition Timing
- **IGNITION COIL FAILURE**
 - Internal Breakdown
 - Low Secondary "High Voltage" Output

17

IGNITION SYSTEM FAILURES - POINT TYPE

- **POINT CLOSURE**
 - Change of Initial Ignition Timing (retards Timing)
- **POINT BURN/PITTED**
 - Limited Current Flow/Low Voltage Output
- **IGNITION RESISTOR FAILURE**
 - Becomes High Resistance with Poor Performance
- **CAPACITOR FAILURE**
 - Changes Value (Open) with Poor Performance

18

IGNITION SYSTEM FAILURES - HEI

- **ELECTRONIC MODULE***
 - Electronic Failure Preventing Operation (Sometimes with Engine Backfires)
 - Missing or Wrong Thermal Conducting Compound
 - Required Under Module
 - **LOST OF COIL GROUND**
 - Ignition Failure with Erratic or Non Operation
 - **IGNITION COIL***
 - Ignition Failure with Erratic or Non Operation
 - **WRONG DISTRIBUTOR**
 - Original Dist. Replaced with Car Type Dist. Which Limits Performance (Wrong Mech. & Vac. Advance)
 - **SHORTED TACH CIRCUIT**
 - Short in Tachometer Wiring/Unit can Disable Ignition
- Note: * Highly Recommended as Spare Component

19

SPECIALTY SPARK PLUGS (PLATINUM, SPLIT FIRE, ETC)

- **PRIMARY ADVANTAGE**
 - REQUIRES LESS ARC-OVER VOLTAGE
 - ALLOWS SPARK GAP TO BE JUMPED A HIGHER PERCENTAGE OF THE TIME (PARTICULARLY IN WEAK SYSTEMS)
- **PRIMARY DISADVANTAGE**
 - LOWER ARC-OVER VOLTAGE /LESS ENERGY WHEN IT FIRES
 - ONLY PROVIDES PERFORMANCE IMPROVEMENTS IN WEAK IGNITION SYSTEMS BY REDUCING THE NUMBER OF MISFIRES (OVER SHADOWS REDUCED SPARK ENERGY)
 - MASK PROBLEMS INHERENT IN WEAK IGNITION SYSTEMS
- **WHY THEY WORK**
 - PLATINUM METAL REQUIRES LESS ARC-OVER VOLTAGE THAN STEEL OF SAME CONFIGURATION
 - SPARK JUMPS BETER TO & FROM "POINTY OBJECTS"
 - "V" SHAPE GIVE MORE "POINTY" AREAS

Ref: Jacobs Electronics Team News, Issue 2 (9/94)

20


HEI GENERAL TEST PROCEDURE ON VEHICLE TEST

- CONNECT SPARK PLUG WIRE TO GROUND HEI TESTER
 - SPARK PRESENT: IGNITION SYSTEM OK (TEST COMPLETED)
 - NO SPARK: IGNITION SYSTEM PROBLEM (CONTINUE TEST)
- REMOVE PLASTIC COIL COVER (TOP OF DIST. CAP-2 SCREWS) & CONNECT 12v TEST LITE BETWEEN DIST. TACK TERMINAL & GRD
 - TURN ON IGNITION: TEST LITE SHOULD GLOW
 - IF NOT: CHECK FOR +12v AT DIST. BAT TERMINAL
 - NO POWER: CIRCUIT WIRING OR IGN. SWITCH PROBLEM
 - POWER PRESENT: PRIMARY COIL IS OPEN (REPLACE COIL)
 - IF TEST LITE GLOWS, CRANK ENGINE: LITE SHOULD FLICKER
 - FLICKER INDICATES MODULE & PICK-UP COIL FUNCTIONAL
 - REMOVE DIST. CAP & TEST FOR SPARK AT CENTER TERMINAL USING HEI TESTER & JUMPER WIRE
 - SPARK INDICATES ROTOR NOT WORKING (REPLACE)
 - NO SPARK INDICATES COIL NOT WORKING (REPLACE)
 - NO FLICKER, PERFORM MODULE TEST

Note: Clean & Check Terminals for Tightness Before Test

21

THE IGNITION CIRCUIT



22

PREVENTITIVE MAINTENANCE ITEMS

"IGNITION"

- REPLACE OEM IGNITION WIRES or REPLACE WITH PERMANENT AFTER-MARKET METALLIC CONDUCTOR/SILICON WIRES - 20K
- REPLACE SPARK PLUGS
 - HEI - 20K
 - POINTS - 10K
- VACUUM ADVANCE - VERIFY SMOOTH ACTION - 5K
- MECHANICAL ADVANCE - INSPECT FOR WEAR & ACTION - 5K
- DISTRIBUTOR SHAFT BEARING
 - INSPECT FOR RADIAL WEAR - 10K
 - REBUILD DISTRIBUTOR - 80K
- DISTRIBUTOR CAP*/ROTOR* - INSPECT & CLEAN - 5K
- HEI MODULE* & COIL* - REPLACE FAILURES - AS REQD
- POINTS*, CAPACITOR* & ROTOR* - REPLACE - 10K
- COIL* (POINT SYSTEM) - REPLACE FAILURES - AS REQD

NOTE: *Always Carry a Known Good Spare

